



















# ***Assembling instruction***




|                                                                                            |                                                                                           |                                                                                           |                                                                                       |                                                                                                        |
|--------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------|
|           |         |  L      |  R |                     |
| ① x 4                                                                                      | ② x 4                                                                                     | ③ x 1                                                                                     | ④ x 1                                                                                 | ⑤ x 1                                                                                                  |
|  3.5x30 |  M8x16 |  M8x20 |  |  $\varnothing 30$ |
| ⑥ x 20                                                                                     | ⑦ x 4                                                                                     | ⑧ x 20                                                                                    | ⑨ x 1                                                                                 | ⑩ x 4                                                                                                  |
|         |  M8x70 |        |  |  M8x60            |
| ⑪ x 4                                                                                      | ⑫ x 2                                                                                     | ⑬ x 2                                                                                     | ⑭ x 2                                                                                 | ⑮ x 4                                                                                                  |
|         |  M8x50 |  M8x30 |                                                                                       |                                                                                                        |
| ⑯ x 4                                                                                      | ⑰ x 4                                                                                     | ⑱ x 4                                                                                     |                                                                                       |                                                                                                        |




|       |       |       |       |
|-------|-------|-------|-------|
|       |       |       |       |
| A x 1 | B x 1 | C x 1 | D x 1 |
|       |       |       |       |
| E x 1 | F x 1 | G x 1 | H x 1 |

1.




2.

Screw all bolts 50%







3.


Screw all bolts 100%



4.



5.






x2

16x 2

9.



10.

