



# K01-1

A



1PCS

B



1PCS

C



M6\*20

4PCS

D



ø6\*16

4PCS

E



M6

1PCS

G



4PCS

STEP: 1

OK

