




















ASSEMBLE INSTRUCTION

6018H

<p>1</p> 	<p>2</p> 	<p>3</p> 	<p>A</p>		<p>1PC</p>
<p>4</p> 	<p>5</p> 	<p>6</p> 	<p>B</p>		<p>5PCS</p>
			<p>C</p>		<p>5PCS</p>
			<p>D</p>		<p>1PC</p>
			<p>E</p>		<p>1PC</p>
			<p>F</p>		<p>1PC</p>
			<p>G</p>		<p>1PC</p>
			<p>H</p>		<p>1PAIR</p>
			<p>I</p>	 <p>M6*10mm</p>	<p>5PCS</p>
			<p>J</p>	 <p>M6*20mm</p>	<p>4PCS</p>
			<p>K</p>	 <p>M6*25mm</p>	<p>2PCS</p>
			<p>L</p>	 <p>M8*50mm</p>	<p>4PCS</p>
			<p>M</p>	 <p>M1 M2</p>	<p>2PCS</p>